


workflow

Differential Scanning Calorimeter (DSC)

Open instrument and setup test conditions



Put the reference pan at the sensor furthest away from you,
and the sample pan at the sensor closest to you



Press start and wait for the experiment to finish

Close instrument

Switch off RCS90 and wait until the Flange Temperature
is around room temperature



Shut down the DSC instrument



Shut down the computer



Close gas

